


T. 141 R. 2B M. 574 Coordinates: X _____ Y _____
E/431 Corner common to sections 31,32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO BITS (IN TAM. BOG)
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1916 By E. B. Horst
Location filed County Book B P. 304-390
Monument SET 2x4" IRON PROPORTIONAL
1919, E. B. Horst County Book C P. 210 FND. I.M. 2000

Evidence of Subsequent Corner Restoration

Year of search 4/9/84 By Freeman-Humitzsch
Survey Tech - Forester
Fnd 2" i.p. up h2
20' west of G Trail

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

R. oak Maple
17" Twin 6" 7"
N29°W 569°W
49.40' 36.91'
CCLD Tag

Subsequent Corner Restoration X-5

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc # 312351
Set 2" x 24" iron pipe with brass cap and
plastr. base with magnet. Ties: 13" Red
Oak N46°W 43.72'; 88" Red Oak N10°W
77.10'; 12" Red Oak N80°E 36.60'; 2" Iron
pipe N 12°32'16" E 35.03'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____