


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
5/14 33 Corner common to sections 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Bearing Trees

Species	<u>IRONWOOD</u>	<u>BL. OAK</u>	_____
Diameter	<u>5"</u>	<u>8"</u>	_____
Bearing	<u>N10W</u>	<u>N49E</u>	_____
Distance	<u>30 LKS</u>	<u>8 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1927 By ?

Location filed micro film - roll 115 BK 770.122-123

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker

Found 3/4" iron pipe.

Set 2"x24" iron pipe with brass cap and plastic base with magnet.

Bearing Trees, Reference Objects

Species	<u>W. oak</u>	<u>W. Pine</u>	_____
Diameter	<u>14"</u>	<u>16"</u>	_____
Bearing	<u>N16-15W</u>	<u>N70-30W</u>	_____
Distance	<u>106.5'</u>	<u>94.0'</u>	_____

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>Red Oak</u>	<u>Red Oak</u>
<u>12"</u>	<u>10"</u>	<u>12"</u>
<u>N 58 W</u>	<u>N 24 E</u>	<u>N 48 E</u>
<u>109.65'</u>	<u>61.34'</u>	<u>82.72'</u>

Subsequent Corner Restoration 2-11

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PINE GABLES OF THE NORTH

JOHN M. GREENE 1928?

PLAT - BLAIRS PINE GABLES

JOHN X. STARK 1961

1989 Certificate - David Landecker

Doc # 312348