


T. 141 R. 28 M. 5th Coordinates: X _____ Y _____
5632 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument Post

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	
<u>5"</u>	<u>5"</u>	
<u>N6W</u>	<u>N59E</u>	
<u>37LKS</u>	<u>28LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1912 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK "B" P. 265-269
 Monument SET CORNER PROPORTION ALLY
1916 E.R. HARST BOOK "B" P. 384-390 PULLED TODD'S
POST - SET 2 1/2 x 4 1/2" GALV. I.P. W/KAP
also on microfilm - roll 115 BK 77 P. 89-90

Species	Bearing	Distance
<u>POPLAR</u>	<u>POPLAR</u>	<u>BASSWOOD</u>
<u>8"</u>	<u>8"</u>	<u>8"</u>
<u>S65W</u>	<u>S45E</u>	<u>S71W</u>
<u>9.50'</u>	<u>13.50'</u>	<u>73.90'</u>

R 1912 R 1916

Evidence of Subsequent Corner Restoration
 Year of search 1942 By JOHN CURO
COUNTY BOOK "D" P. 286 I.M.

1912 - also on microfilm - roll 105 BK 69 P. 87

Species	Bearing	Distance
<u>BASSWOOD</u>	<u>F.M.</u>	<u>W. OAK</u>
<u>7"</u>	<u>WIT. MONU.</u>	<u>4"</u>
<u>N24-15E</u>	<u>SOUTH</u>	<u>N47-43W</u>
<u>66.40'</u>	<u>25'</u>	<u>90.10'</u>

1942 ties

Subsequent Corner Restoration 2-9
 Year surveyed 1925 By John Greene
 Location filed Microfilm - roll 105 BK 69 P. 94
 Monument Galv. pipe with cap

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

1989 Certificate - David Landecker
Doc. #312350
Set 2" x 24" Iron pipe with brass cap
and plastic base with magnet. Ties:
12" Red Oak N42W 90.17'; 9" Birch
N12E 77.16'; 10" Red Oak N52E 75.54'