


Index No. A-B 15

CASS COUNTY LAND CORNER RECORD

T. 241 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC on Corner common to sections _____
N-S 1/4 LIME ON REESTABLISHED MEANDER LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918 SMC

Original monument 1X36" I.P. W/ BRASS 53 153
CAP 1918

Bearing Trees

Species	<u>ELM</u>	<u>ELM</u>	_____	_____
Diameter	<u>14"</u>	<u>8"</u>	_____	_____
Bearing	<u>S30E</u>	<u>S82-45W</u>	_____	_____
Distance	<u>63 LKS</u>	<u>69 LKS</u>	_____	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____