


Index No. B 1-2

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X 753536.05 Y 194460.02
SMC ON N Corner common to sections 6
N 1/16 LINE



O = Corner

EXISTING SURVEYS

Original Government Survey	
Year surveyed	<u>1918</u>
Original monument	<u>1436" 1/4 W / 20355 N</u>
	<u>56' N SMC</u>
	<u>56' N</u>
Bearing Trees	
Species	<u>Poplar</u> <u>White Oak</u>
Diameter	<u>8"</u> <u>12"</u>
Bearing	<u>S31-30E</u> <u>N56-15W</u>
Distance	<u>154KS</u> <u>203KS</u>

Original Evidence Found	
Year of search	By
Monument found	
Original Bearing Trees Found	
Species	
Diameter	
Bearing	
Distance	

Subsequent Corner Restoration				
Year surveyed	<u>12/03</u>			
Location filed	<u>USFS Cass Lake</u>			
Monument <u>Found GLO bent, set Alum.</u>				
<u>cap rod monument. A cot L was</u>				
<u>fr. 1 ed.</u>				
<u>Steel post, East 2.54'</u>				
Bearing Trees, Reference Objects				
Species	<u>Basswood</u>	<u>Basswood</u>	<u>Oak</u>	<u>Steel Post</u>
Diameter	<u>12"</u>	<u>14"</u>	<u>12"</u>	<u>8'</u>
Bearing	<u>N88°W</u>	<u>S13°W</u>	<u>S35°E</u>	<u>West</u>
Distance	<u>131.61'</u>	<u>60.56'</u>	<u>43.40'</u>	<u>3.52'</u>

Evidence of Subsequent Corner Restoration	
Year of search	By
Bearing Trees, Reference Objects	

B-1, 2

Subsequent Corner Restoration	
Year surveyed	By
Location filed	
Monument	

Evidence of Subsequent Corner Restoration Found	
Year of search	By