


Index No. B-C 14-15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SMC ON Corner common to sections \_\_\_\_\_  
E-W 1/4 LINE OF SE 1/4 NW 1/4



O = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918  
Original monument 1X36" 1/2 P. W. / ~~BRASS~~ SMC TR 1537 53  
TR 1037  
CAP 1918

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. OAK H. OAK \_\_\_\_\_  
Diameter 5" 14" \_\_\_\_\_  
Bearing N 61 E S 56 E \_\_\_\_\_  
Distance 62 LKS 68 LKS \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed Apr 2002 By T. Freeman #21367  
Location filed \_\_\_\_\_  
Monument Cert. of Surv. shows Mon. Found

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_