Index No. C 2

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X (E) 454178.19 Y (N) 193153.51

C.W. 1/16 Corner common to sections 6



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X 36" I.P. w/ BRASS CAP C — W 1/16 / 56 / 1918 — C

Original Evidence Found

Year of search 2/00 By USFS

Monument found GLO pipe

Bearing Trees

Species	CEDAR	CEDAR		
Diameter	10"	10"		
Bearing	S21-30W	N44-15W		
Distance	26 LKS	22 LKS		

Original Bearing Trees Found

Species	Cedar	Cedar		New Cedar
Diameter	3' stp	24"		10"
Bearing	S21°30'W	N44°W		S36°W
Distance	17.16'	14.52'		33.85'

Subsequent Corner Restoration

Year surveyed 9/03 By NLS&M

Location filed USFS Cass Lake

Monument Found GLO pipe, replace with 2½" pipe w/brass cap. GLO c 2000 witnesses good. A C of L was filed

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Spruce	Steel post	Steel Post	
Diameter	7½"	8'	8'	
Bearing	N82°E	S2°E	N87°E	
Distance	18.17'	4.8'	3.93'	

Bearing Trees, Reference Objects

C-2

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared #480063 By #16089

Filed at CCRO Date 2/12/04