

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E 141 Corner common to sections 1 AND 6-141-28



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

 Bearing Trees
 Species W. PINE W. PINE
 Diameter 25" 20"
 Bearing N56E N56 1/2 W
 Distance 14 LKS 74 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1915 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK 'D' P 169-177
 Monument FND OLD GOVT B.T.S: 25" W. PINE N56E
14 LKS, STUMP 20" W. PINE N56-30W 74 LKS SET HUB
1915- HORST- microfilm- roll 1105 BK 60 P. 140 Fnd
B.T.S as above- set square hub. P143- set
2" x 48" capped I.M.
 Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration
 Year of search 1918 By GLO
FND 2" I.P. SET 1X36" I.P. W/ BRASS CAP
AND FND NE BIT. STUMP.
 114
 51/56
 1918

 Bearing Trees, Reference Objects
R.OAK R.OAK
20" 5"
N58E N73-30W
265 LKS 100 LKS

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

