Index No. D 20

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SE 1/16 Corner common to sections 2




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. w/ BRASS CAP

SE 1/16 S2 1918

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | MAPLE | BIRCH | | |
| Diameter | 10" | 6" | | |
| Bearing | N17-30E | S30-45W | | |
| Distance | 39 LKS | 20 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____