


T. 141 R. 29 M. 5TH Coordinates: X. \_\_\_\_\_ Y. \_\_\_\_\_  
MC# 33 Corner common to sections 3, 10



EXISTING SURVEYS

**Original Government Survey**  
Year surveyed 1873  
Original monument POST

**Bearing Trees**  
Species W. ASH W. OAK  
Diameter 7" 6"  
Bearing S10W NORTH  
Distance 8 LKS 10 LKS

**Original Evidence Found**  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
Year surveyed 1918 By GLO  
Location filed SEC. OF STATE  
Monument 1X36" I.P. w/BRASS CAP - FWD DECAYED WOOD  
STAKE AND S.W. BIT STUMP AND STUMP HOLE NORTH  
TIHIN RRQW  
53 MC  
510 MC  
1918

**Bearing Trees, Reference Objects**  
Species POPULAR W. OAK  
Diameter 8" 10"  
Bearing S16-15W N44-15W  
Distance 190 LKS 142 LKS

**Evidence of Subsequent Corner Restoration**  
Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Subsequent Corner Restoration**  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_