Index No. E 17-18

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

MC # 29 Corner common to sections 2, 11




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1873

Original monument POST

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | |
|---|---|---|
| Species | B. OAK | B. OAK |
| Diameter | 15" | 15" |
| Bearing | N50E | S33E |
| Distance | 22 LKS | 83 LKS |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed SEC. OF STATE

Monument FND BOTH BITS. NE IS N50E NOT N40E.
SET 1X36" I.P. W/BRASS CAP. T141N R29W

MC 52/11 1918

### Bearing Trees, Reference Objects

| | | |
|---|---|---|
| Species | W. OAK | BL. OAK |
| Diameter | 10" | 18" |
| Bearing | N63E | S40E |
| Distance | 29 LKS | 75 LKS |

### Evidence of Subsequent Corner Restoration

Year of search Nov 2001 By R. Nustesen

Cert. of Surv. shows mon. set found

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____