


Index No. E 20-21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E-E 1/4 Corner common to sections 2, 11  
AP# 21442, AP# 31402, AP# 41273



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1918

Original monument 1x36" I.P. W/BRASS TR 1273 TR 1402  
CAP APY APZ  
TR 1442  
APR  
511  
1918

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

○ = Corner

**Subsequent Corner Restoration**

Year surveyed 1923 By Miss. Hwy Dept.

Location filed R/W map in Recorder's office - 15 mi. E of

Monument Walker to 12 mi. W. of Remy  
corner on road

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_