

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument BST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>BIRCH</u>	<u>CEDAR</u>	<u>BIRCH</u>	<u>B. ASH</u>
Diameter	<u>10"</u>	<u>6"</u>	<u>12"</u>	<u>5"</u>
Bearing	<u>N78E</u>	<u>N30W</u>	<u>S41W</u>	<u>S41E</u>
Distance	<u>9 LKS</u>	<u>21 LKS</u>	<u>20 LKS</u>	<u>41 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SEC. OF STATE.
Monument FOUND REMAINS OF ORIG. STAKE AND NE, SE, AND SW B.T.S. 1X36" 11P. W/BRASS CAP 714IN. RR2W

Evidence of Subsequent Corner Restoration

Year of search 8/2001 By CCSO
Found 1" ODIP, down 1.0', 8' E S. of & Hwy # 200

Species	Bearing Trees, Reference Objects			
	<u>CEDAR</u>	<u>B.L. ASH</u>	<u>CEDAR</u>	<u>CEDAR</u>
Diameter	<u>5"</u>	<u>8"</u>	<u>10"</u>	<u>7"</u>
Bearing	<u>N47E</u>	<u>S25E</u>	<u>S44 1/2 W</u>	<u>N22 3/4 W</u>
Distance	<u>20 LKS</u>	<u>49 LKS</u>	<u>57 LKS</u>	<u>31 LKS</u>

Species	Bearing Trees, Reference Objects			
	<u>Ash</u>	<u>Ash</u>	<u>Balsam</u>	<u>Ash</u>
Diameter	<u>6"</u>	<u>8"</u>	<u>8"</u>	<u>5"</u>
Bearing	<u>N20° E</u>	<u>S10° E</u>	<u>S32° W</u>	<u>N33° W</u>
Distance	<u>44.47*</u>	<u>45.51*</u>	<u>46.95*</u>	<u>55.58*</u>

*distance to double head nail

E-21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____