


Index No. E 5-6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

W-W 164 Corner common to sections 5, 8
AP# 3 1478, AP# 4 1482



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1.36" I.P. w/ BRASS CAP

Bearing Trees SB 1918

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BUTLER SMITH HWY ENGINEER - 1921

Set iron pipe with brass cap. TIES:

9" Oak N 10 E 35.8'; 12" Oak S 45° 45' E

49.9'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____