


Index No. E-F 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N-NE 1/4 Corner common to sections 12  
AP#1 1627, AP#4 1522



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1918

Original monument 1x36" I.P.W./GLASS CAP 512

Bearing Trees 1918

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed 1987 By Cass County & USFS

Location filed Corner Certificate - Doc #

Monument Found GLASS cap. Distance to S. checks

Bearing Trees, Reference Objects

Species	<u>Red oak</u>	<u>Red oak</u>	<u>Burr oak</u>	<u>Fiberglass</u>
Diameter	<u>10"</u>	<u>11"</u>	<u>5"</u>	<u>sign posts</u>
Bearing	<u>N 58° W</u>	<u>N 10° E</u>	<u>S 26° W</u>	<u>N and W</u>
Distance	<u>29.00'</u>	<u>24.41'</u>	<u>83.78'</u>	<u>4.0', 4.0'</u>

Scribed "X 87"

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

11395  
1990 Certificate - Watt Curo, RLS # ~~317853~~  
Doc. # 317853

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_