Index No. E-F 7

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections _____

RE-ESTABLISHED MEANDER LINE ON N-S 1/4 LINE




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/BRASS CAP

C
S8 | S8
C
SMC
1918

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | BASSWOOD | BALSAM | | |
| Diameter | 14" | 6" | | |
| Bearing | N54-15E | N25-45W | | |
| Distance | 31 LKS | 7 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____