


Index No. G-10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5th Coordinates: X _____ Y _____
CW 1/4 Corner common to sections 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" I.P. w/ BRASS CAP w 1/4 C 59 C 1918

Bearing Trees

Species	Bearing	Distance
<u>W. OAK</u>	<u>9"</u>	<u>61 LKS</u>
<u>W. OAK</u>	<u>7"</u>	<u>42 LKS</u>
<u>NB-30E</u>		
<u>SS-30W</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 9/2/87 By DNR
Location filed Field notes (also in trap file)
Monument End GLO Brass cap monument flush w/ ground in center of trail.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>2-4"</u>	<u>244°</u>	<u>27.83'</u>
<u>Maple</u>	<u>7"</u>	<u>15°</u>	<u>36.01'</u>
<u>Red oak</u>	<u>22"</u>	<u>103°</u>	<u>66.63'</u>

DNR DISC'S in trees

Evidence of Subsequent Corner Restoration

Year of search 9/8/87 By Jerry Freeman - f DNR
left corner as found - placed 7' steel sign post and survey marker sign East 5' Certificate - Dec 87
no sign of 1918 ties
converted Azimuths to Bearings

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Twin Maple</u>	<u>2"-4"</u>	<u>561°W</u>	<u>27.83'</u>
<u>Maple</u>	<u>7"</u>	<u>N16°E</u>	<u>36.01'</u>
<u>Red Oak</u>	<u>22"</u>	<u>S80°E</u>	<u>66.63'</u>

scribed "X" (scribed "CW 1/4 59 BT")

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1990 Certificate - Walter Cunn, RLS 11395
Doc. # 317854

Remuneration certificate prepared _____

By _____

Filed at _____ Date _____