Index No. G 3-4

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC ON E-W 1/4 LINE Corner common to sections 7




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. w/BRASS CAP C 57/57 C 1918 SMC

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | ASH | POPLAR | | |
| Diameter | 7" | 18" | | |
| Bearing | SOUTH | N79W | | |
| Distance | 175 LKS | 355 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____