


Index No. 68

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 57H Coordinates: X _____ Y _____
C.E. 116 Corner common to sections 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918 E 1/4
Original monument 1x36" I.P. w/brass cap 58 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>ASH</u>	<u>ASH</u>
Diameter <u>10"</u>	<u>8"</u>
Bearing <u>S 73 E</u>	<u>S 31 W</u>
Distance <u>123.45</u>	<u>147.65</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1980 By Gary Stevenson
Found 1918 6.0 iron pipe with marked brass cap.

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Oak</u>	<u>Ash snag</u>	<u>Ash</u>
<u>6"</u>	<u>9"</u>	<u>12"</u>	<u>6"</u>
<u>N 61 W</u>	<u>S 51 W</u>	<u>S 31 W</u>	<u>S 85 E</u>
<u>58.02'</u>	<u>44.53'</u>	<u>97.02'</u>	<u>106.87'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260980

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____