


Index No. G-H 17

CASS COUNTY LAND CORNER RECORD

T. M1 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 34 Corner common to sections 10,11



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument POST

**Bearing Trees**

Species	<u>W. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>30"</u>	<u>24"</u>	_____
Bearing	<u>N66W</u>	<u>S40W</u>	_____
Distance	<u>115 LKS</u>	<u>122 LKS</u>	_____

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed 1918 By GLO  
 Location filed SEC. OF STATE  
 Monument SET 1X36" I.P. W/BRASS CAP  
NO SIGN OF ORIG.

510 511  
 T141N R29W  
 1918

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>OAK</u>	<u>POPLAR</u>	_____
Diameter	<u>8"</u>	<u>5"</u>	_____
Bearing	<u>S33-45E</u>	<u>S18-15W</u>	_____
Distance	<u>246 LKS</u>	<u>240 LKS</u>	_____

**Bearing Trees, Reference Objects**

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_