


Index No. H 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
C.S. 1/16 Corner common to sections 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1X36" I.P. w/ BRASS
CAP 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species CEEDAR POOLAR
Diameter 6" 5"
Bearing N47-30W S12W
Distance 44 LKS 22 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1981 By GARY STEVENSON
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Balm Gilead</u>	<u>Cedar</u>	<u>Ash</u>
<u>5"</u>	<u>18"</u>	<u>10"</u>	<u>5"</u>
<u>S64W</u>	<u>S12W</u>	<u>S9E</u>	<u>S84E</u>
<u>18.12'</u>	<u>14.53'</u>	<u>24.97'</u>	<u>30.25'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260982

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____