


Index No. H 8

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S.E. 1/16 Corner common to sections 8



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918 SE 1/16 S8  
Original monument X36" 1/4 W / BRASS 1918  
CAP

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. OAK W. OAK  
Diameter 9" 9"  
Bearing N45W S5 1/2 W  
Distance 25 LKS 31 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1981 By Gary Stevenson  
Found GLO monument in good condition.  
12" W. Oak S 6 W 20.46'.

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
W. Oak W. Oak stump W. Oak Ash  
7" 18" 13" 7"  
N48W N45W N25E S68E  
38.72' 16.50' 90.63' 42.96'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - GARY STEVENSON - 1981  
DOC. # 260983

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_