Index No. J 5-6   CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X_____ Y_____
MC #36 Corner common to sections 8,17 _____

O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873 _____
Original monument Post _____

Bearing Trees

Species	TAM.	TAM.		
Diameter	5"	6"		
Bearing	N26E	S7E		
Distance	11 LKS	11 LKS		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1918 By 610
Location filed SEC. OF STATE
Monument PROPORTIONAL POST SET - NO EVIDENCE OF ORIG.
ALSO SET ONE ON SHORE   T 141 N R29W
OF LAKE   MC | S8
                         | S17
                         | R29W
                     1918

Bearing Trees, Reference Objects

Species	CEDAR	CEDAR	
Diameter	20"	18"	
Bearing	N6½E	S27-45E	
Distance	43 LKS	99 LKS	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____