


Index No. J 5-6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

MC. _____ Corner common to sections _____
ON E. SHORE HAINES LAKE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" 1/4" W/BASS MC / 517
CA 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____	_____
Diameter	<u>10"</u>	<u>8"</u>	_____	_____
Bearing	<u>EAST</u>	<u>S21-15E</u>	_____	_____
Distance	<u>15 LKS</u>	<u>8 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____