


Index No. J 8

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E 116 Corner common to sections 8, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1918
 Original monument 1x36" I.P. W/BRASS E/116 SB
CAP 517
1918

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species W. OAK W. OAK
 Diameter 12" 10"
 Bearing N 9 1/2 E S 83-15 E
 Distance 96 LKS 115 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1980 By Gary Stevenson
found GLO monument in good condition.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
W. Oak W. Oak W. Oak
18" 10" 18"
N 9 1/2 E S 49 E S 83 1/4 E
63.36' 44.97' 75.90'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260987

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____