Index No. K 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

N 1/16 Corner common to sections 17,18



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" 16P. W/BRASS CAP

N 1/16 S18/S17 1918

Bearing Trees

Species	CEDAR	CEDAR		
Diameter	13"	11"		
Bearing	N46E	S59-30W		
Distance	8LKS	16LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1963 By Pete Meyer

Found GLO monument in good condition.
13" Cedar N46E 8 lks now stump.
11" Cedar S59°30'W 16 lks now stump.

Bearing Trees, Reference Objects

Species	Ash	Ash	Cedar	
Diameter	4"	4"	9"	
Bearing	N81E	N 61 W	S 11 E	
Distance	7.6'	6.45'	24.3'	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____