


Index No. 617

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E 14 15 Corner common to sections 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Bearing Trees

Species	<u>BIRCH</u>	<u>POPLAR</u>	_____
Diameter	<u>2"</u>	<u>4"</u>	_____
Bearing	<u>N22W</u>	<u>S60E</u>	_____
Distance	<u>16 LKS</u>	<u>48 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SEC. OF STATE
Monument 1X36" I.P. W/BRASS CAP PROPORTIONATE POSITION
14
515 514
1918

Evidence of Subsequent Corner Restoration

Year of search 1980 By Gary Stevenson
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>TAM</u>	_____
Diameter	<u>14"</u>	<u>4"</u>	_____
Bearing	<u>S30E</u>	<u>S87W</u>	_____
Distance	<u>128 LKS</u>	<u>54 LKS</u>	_____

Bearing Trees, Reference Objects

Cedar	Cedar	Cedar	Cedar
8"	10"	8"	20"
N58W	N78E	S86W	S30E
18.11'	16.88'	11.12'	128 LKS
			GLO BT

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260998

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____