Index No.	CORNER RECORD
	<u> </u>
T. 141 R. 29 M. 51H Coordinates: X E116 Corner common to sections 15, 22	
Original Government Survey	SURVEYS Original Evidence Found
	Year of search By+
Year surveyed 1918 Original monument 1 x 36" 1 11. w   BRASS E   51.5  CAP 1918	Monument found
Species Bl. oak Bl. oak	Original Bearing Trees Found O = Corner Species
Diameter /9" 16"	Diameter
Bearing <u>N17-48E 568-15W</u>	Bearing
Distance 180 LKS 170 LKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1980 By Gary Stevenson  Location filed  Monument Found GLO monument in good  condition.	Year of search By
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species         W. Oak         N. Pine         Oak stump         W. Oak           Diameter         7"         14"         30"         10"           Bearing         N 17 W         S 88 W         N 17 4 F         N 81 F           Distance         23.81'         49.93'         1/8.8'         19.92'           GLO         BT	
Subsequent Corner Restoration  Year surveyed By  Location filed Monument	Evidence of Subsequent Corner Restoration Found  Year of search By CERTIFICATE - CART STEVENSON -1981  Doc. # 261008
Remonumentation certificate prepared	By