Index No. P19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

C14 Corner common to sections 23



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/BRASS CAP

C14 523
1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Tam.	Cedar		
Diameter	4"	8"		
Bearing	N40E	S4E		
Distance	23 LKS	173 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 4/23/86 By Freeman - Hemmitzsch

Fnd brass cap laying down - set upright.
Fnd 16" Tam N40E 15' w/old tag in.
This is possible orig B.T. and also possible
1936 CCC "spruce" 8" N51E 15.5'
also possible Cedar S4E

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

put CCLD tag
on 16" Tam
N40E
15'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____