


Index No. R 19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 26 Corner common to sections 23, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>N. PINE</u>	<u>N 1/4</u>	<u>N. PINE</u>
<u>10"</u>	<u>10"</u>	
<u>NORTH</u>	<u>SOUTH</u>	
<u>8 LKS</u>	<u>7 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SEC. OF STATE
Monument FIND STUMPS OF BOTH CORN. BITS (NICE AND SW) SET 1X36" I.P. W/ BRASS CAP

Evidence of Subsequent Corner Restoration

Year of search 1986 4/23 By Freeman-Hummitzsch
Find brass cap monument up 6", Norway plantation SW
orig bit. stump south 5'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. PINE</u>	<u>6"</u>	<u>N 26-15E</u>	<u>38 LKS</u>
<u>J. PINE</u>	<u>6"</u>	<u>S 46-45W</u>	<u>137 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Twin Roak</u>	<u>7", 10"</u>	<u>N 66W</u>	<u>6.70'</u>
<u>Roak</u>	<u>11"</u>	<u>S 27E</u>	<u>18.90'</u>
<u>Roak</u>	<u>15"</u>	<u>N 79E</u>	<u>26.80'</u>
			<u>old FSLP</u>
			<u>CCLD tag</u>
			<u>old rusted tag</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 310671
Found 1" iron monument with brass cap.
Ties: 7" Maple N 26 W 80.57'; 5" Norway
Pine S 37 W 37.92'; 10" Red Oak N 65 W
39.20'.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____