


Index No. T 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 29 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>MAPLE</u>	<u>OAK</u>	_____
Diameter	<u>4"</u>	<u>10"</u>	_____
Bearing	<u>N33E</u>	<u>S44W</u>	_____
Distance	<u>11 LKS</u>	<u>11 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Burr Oak</u>	<u>Red Oak</u>
Diameter	<u>5"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>N74E</u>	<u>S46E</u>	<u>S15E</u>
Distance	<u>91.12'</u>	<u>69.85'</u>	<u>65.65'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc # 312349

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____