


Index No. V 19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 35 Corner common to sections 26, 35



○ = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument Post

**Bearing Trees**  
 Species PINE STUB  
 Diameter 12"  
 Bearing S60E  
 Distance 46 LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1989 By David Landecker  
 Location filed \_\_\_\_\_  
 Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>N. Pine</u>	<u>N 87 W</u>	<u>31.76'</u>
<u>N. Pine</u>	<u>S 32 W</u>	<u>18.30'</u>
<u>N. Pine</u>	<u>N 68 E</u>	<u>25.78'</u>

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 312154

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_