


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees	
Species <u>W. Pine</u>	<u>W. Pine</u>
Diameter <u>20"</u>	<u>24"</u>
Bearing <u>N40E</u>	<u>N55W</u>
Distance <u>13 LKS.</u>	<u>39 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration  
 Year surveyed 1983 By David Claypool  
 Location filed Corner Certificate  
 Monument set 2x60" l.p. w/3" brass cap  
at proportioned position between NW & NE  
corners.

Evidence of Subsequent Corner Restoration  
 Year of search 1988 By David Landecker  
 Found 2" iron monument with brass cap  
(USFS).

Bearing Trees, Reference Objects		
Species <u>N. Pine</u>	<u>J. Pine</u>	<u>R. oak</u>
Diameter <u>5"</u>	<u>14"</u>	<u>10"</u>
Bearing <u>N17W</u>	<u>S48E</u>	<u>S35W</u>
Distance <u>25.30'</u>	<u>37.43'</u>	<u>13.65'</u>

Bearing Trees, Reference Objects		
<u>N. Pine</u>	<u>N. Pine</u>	<u>J. Pine</u>
<u>8"</u>	<u>5"</u>	<u>15"</u>
<u>N 17 W</u>	<u>S 85 E</u>	<u>S 48 E</u>
<u>25.32'</u>	<u>19.64'</u>	<u>37.45'</u>
<u>(1983 BT)</u>		<u>(1983 BT)</u>

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - David Claypool - Filed by USFS 1984  
Doc. # 279155 dated 1983  
1989 Certificate - David Landecker  
Doc. # 311175

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_