


Index No. V 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees	
Species <u>W. Pine</u>	<u>Tam</u>
Diameter <u>8"</u>	<u>3"</u>
Bearing <u>N78 1/2 E</u>	<u>N34 W</u>
Distance <u>58 LKS</u>	<u>17 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Found 2" iron monument with brass cap (USFS).

Bearing Trees		Reference Objects	
Species <u>Tamarack</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>7"</u>	<u>17"</u>	<u>10"</u>	<u>14"</u>
Bearing <u>N37 W</u>	<u>N47 E</u>	<u>S79 E</u>	<u>S22 W</u>
Distance <u>37.39'</u>	<u>48.44'</u>	<u>65.99'</u>	<u>53.44'</u>
<u>(1964 BT)</u>	<u>(1964 BT)</u>		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OGDEN - 1964

1989 Certificate - David Landecker
Doc. # 311172

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____