


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. LINE</u>	
<u>24"</u>	<u>30"</u>	
<u>N 81 1/2 E</u>	<u>S 45 W</u>	
<u>42 LKS</u>	<u>51 LKS.</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>MAPLE</u>	<u>7"</u>	<u>N 24 W</u>	<u>96.05'</u>
<u>MAPLE</u>	<u>8"</u>	<u>S 85 W</u>	<u>36.35'</u>
<u>MAPLE</u>	<u>7"</u>	<u>S 44 W</u>	<u>19.42'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311191

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____