


Index No. W-X 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 19 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>12"</u>	<u>14"</u>	_____
Bearing	<u>S13W</u>	<u>S6E</u>	_____
Distance	<u>29 LBS</u>	<u>41 LBS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Burr Oak</u>	<u>Ash</u>
Diameter	<u>9"</u>	<u>10"</u>	<u>8"</u>
Bearing	<u>N84W</u>	<u>S70E</u>	<u>S84W</u>
Distance	<u>37.69'</u>	<u>4.57'</u>	<u>26.00'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 311847

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_