


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
S 14 33 Corner common to sections 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Y. PINE</u>	<u>Y. PINE</u>	
Diameter <u>14"</u>	<u>15"</u>	
Bearing <u>N 87 W</u>	<u>N 17 E</u>	
Distance <u>43 LKS</u>	<u>14 LKS</u>	

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species <u>Red Oak</u>	<u>Birch</u>	<u>Red Oak</u>
Diameter <u>5"</u>	<u>10"</u>	<u>6"</u>
Bearing <u>West</u>	<u>N 89 W</u>	<u>N 58 E</u>
Distance <u>33.45'</u>	<u>51.01'</u>	<u>61.87'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - HOLIDAY STORES
MYRON LANDECKER 1975

1989 Certificate - David Landecker
Doc. # 312159

Dec 2002 T. Freeman # 21367
Cert. of Surv. shows Mon. found