


Index No. 213-14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 57A Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 1 Corner common to sections 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>W. BIRCH</u>	<u>W. BIRCH</u>
Diameter <u>6"</u>	<u>7"</u>
Bearing <u>N 41 E</u>	<u>S 11 E</u>
Distance <u>44 LKS.</u>	<u>27 LKS.</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker  
Location filed \_\_\_\_\_  
Monument Found 1 1/2" iron pipe. Set 3/4" x 2' aluminum rod with stamped aluminum cap inside found 1 1/2" iron pipe.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>N. Pine</u>	<u>W. Pine</u>	<u>MC</u>
Diameter <u>18"</u>	<u>15"</u>	
Bearing <u>N 14 E</u>	<u>S 35 E</u>	<u>S 89° 37' 46" E</u>
Distance <u>54.32'</u>	<u>19.90'</u>	<u>3.38'</u>

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 312161

July 2003 T. Freeman # 21367  
cert. of svy. shows Mon. found

Re monumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_