


T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
S14 36 Corner common to sections 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Y. Pine</u>	<u>W. Pine</u>	_____
Diameter	<u>18"</u>	<u>22"</u>	_____
Bearing	<u>N55W</u>	<u>NR3E</u>	_____
Distance	<u>115 LKS</u>	<u>233 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set 3/4" x 5' aluminum rod with point, 3' stabilizer and stamped aluminum cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>9"</u>	<u>20"</u>	<u>24"</u>
Bearing	<u>N10W</u>	<u>N10E</u>	<u>N23W</u>
Distance	<u>116.05'</u>	<u>148.56'</u>	<u>113.90'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. #311954