


Index No. A 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 57A Coordinates: X _____ Y _____
E 1/16 Corner common to sections 1



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1836" 1" P.W. Brass E 1/16 S36
1917 51

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Cedar Cedar
Diameter 14" 14"
Bearing S 22 1/2 W N 40 1/2 W
Distance 26 LKS 30 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument found 1" x 3/16" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Ash Ash Birch
Diameter 8" 8" 6"
Bearing N 37° 40' W S 47° 45' W S 53° 10' E
Distance 41.99' 50.36' 29.60'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Walter Curo - 1981
Doc. # 265244

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____