


Index No. B 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X 452 863.23 Y 194 461.522  
N<sup>116</sup> Corner common to sections 1 AND 6 - 141-29



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1917 N<sup>116</sup>

Original monument 1x36" I.P. w/BRASS 51/56  
CAP 1917

**Bearing Trees**

Species	<u>OAK</u>	<u>PINE</u>	
Diameter	<u>16"</u>	<u>16"</u>	
Bearing	<u>S 29 1/4 E</u>	<u>N 48 1/2 W</u>	
Distance	<u>51 LKS</u>	<u>70 LKS</u>	

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1981 By Walter Curo

Location filed \_\_\_\_\_

Monument Set 2"x36" iron pipe with brass  
cap.  
CERTIFICATE DOC # 262631

**Evidence of Subsequent Corner Restoration**

Year of search 1/2000 By USFS, R. Mach

Found monument and set sign  
posts

**Bearing Trees, Reference Objects**

Species	<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
Diameter	<u>8"</u>	<u>10"</u>	<u>8"</u>
Bearing	<u>N 51° 18' W</u>	<u>S 79° 16' E</u>	<u>S 18° 21' W</u>
Distance	<u>17.68'</u>	<u>60.15'</u>	<u>41.35'</u>

**Bearing Trees, Reference Objects**

<u>Steel Post</u>	<u>Steel Post</u>	
<u>North</u>	<u>West</u>	
<u>2.7'</u>	<u>3.5'</u>	

B-25

**Subsequent Corner Restoration**

Year surveyed 9/03 By NLSM

Location filed USFS Cass Lake

Monument Found Brass cap monument,  
and lists witnesses as follow.  
A CorL was filed

<u>11" R. Oak</u>	<u>S 18° W</u>	<u>41.31'</u>
<u>9" R. Oak</u>	<u>N 52° W</u>	<u>17.76'</u>
<u>13" R. Oak</u>	<u>S 77° E</u>	<u>60.30'</u>

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - WALT Curo - 1981 Doc # 262631

Remonumentation certificate prepared #480057

Filed at CCRO

By #16089

Date 2/12/04