


Index No. C-D 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

A.P. # 1 Corner common to sections _____

TR 125B



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1x36" W. w/ 1/2" brass TR 125B 1557
LAP S1 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>W. Oak</u>	<u>W. Oak</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>5"</u>
Bearing	<u>S70W</u>	<u>S65E</u>	<u>S12E</u>
Distance	<u>32.99'</u>	<u>20.00'</u>	<u>29.55'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Walter Curo - 1981
Doc. # 262632