


T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 10 Corner common to sections 2, 3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees	
Species <u>TAM.</u>	<u>TAM.</u>
Diameter <u>5"</u>	<u>4"</u>
Bearing <u>S30E</u>	<u>S77W</u>
Distance <u>25LKS</u>	<u>32LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1917 By GLO

Location filed SEC. OF STATE

Monument FIND OLD WOOD STAKE AND BOTH GALT BITS.  
SET 1X36" I.P. W. BRASS CAP.

MC  
53 52  
T141N R30W  
1917

Bearing Trees, Reference Objects	
Species <u>CEDAR</u>	<u>CEDAR</u>
Diameter <u>8"</u>	<u>10"</u>
Bearing <u>S21E</u>	<u>S19 1/2 W</u>
Distance <u>81LKS</u>	<u>65LKS</u>

Evidence of Subsequent Corner Restoration

Year of search 1981 By Walter Curo

Found GLO monument in good condition.

Bearing Trees, Reference Objects		
<u>Cedar</u>	<u>W. Oak</u>	<u>Cedar</u>
<u>14"</u>	<u>6"</u>	<u>16"</u>
<u>S37W</u>	<u>S45E</u>	<u>N85E</u>
<u>43.02'</u>	<u>38.71'</u>	<u>39.84'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - WALT CURO - 1981

Doc. # 262625