


Index No. \_\_\_\_\_

### CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



#### EXISTING SURVEYS

##### Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument \_\_\_\_\_

##### Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
 Monument found \_\_\_\_\_

##### Bearing Trees

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_


##### Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

Index No. E 11

CASS COUNTY LAND CORNER RECORD

T. 141 B. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>14</sup> 9 Corner common to sections 4, 9



○ = Corner

EXISTING SURVEYS

| Original Government Survey |                  |
|----------------------------|------------------|
| Year surveyed              | <u>1873</u>      |
| Original monument          | <u>POST</u>      |
| Species                    | <u>TAM.</u>      |
| Diameter                   | <u>10"</u>       |
| Bearing                    | <u>S23 1/2 W</u> |
| Distance                   | <u>34 LKS</u>    |

| Original Evidence Found      |                |
|------------------------------|----------------|
| Year of search               | _____ By _____ |
| Monument found               | _____          |
| Original Bearing Trees Found | _____          |
| Species                      | _____          |
| Diameter                     | _____          |
| Bearing                      | _____          |
| Distance                     | _____          |

| Subsequent Corner Restoration |  |
|-------------------------------|--|
| Year surveyed                 | <u>1917</u> By <u>GLO</u>  |
| Location filed                | <u>SEC. OF STATE</u>   |
| Monument                      | <u>FIN. ORIG. STAKE IN NW 1/4. STUMP SET 1X36"</u><br><u>1/4. W/BRASS CAP</u> <u>14 54</u><br><u>59</u><br><u>1917</u> |

| Evidence of Subsequent Corner Restoration |   |
|---|---|
| Year of search                            | <u>Jan. 2004</u> By <u>T. Freeman # 21367</u> |
| <u>Cert. of Sur. Shows mon found</u>      |   |
|   |   |
|   |   |
|   |   |

| Bearing Trees, Reference Objects |                             |
|----------------------------------|-----------------------------|
| Species                          | <u>CEDAR</u> <u>CEDAR</u>   |
| Diameter                         | <u>10"</u> <u>10"</u>       |
| Bearing                          | <u>N36 1/4 W</u> <u>S2E</u> |
| Distance                         | <u>28 LKS</u> <u>36 LKS</u> |

| Bearing Trees, Reference Objects |  |
|----------------------------------|--|
|                                  |  |
|                                  |  |
|                                  |  |
|                                  |  |

| Subsequent Corner Restoration |                |
|-------------------------------|----------------|
| Year surveyed                 | _____ By _____ |
| Location filed                | _____          |
| Monument                      | _____          |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |
|                               |                |

| Evidence of Subsequent Corner Restoration Found |                |
|---|----------------|
| Year of search                                  | _____ By _____ |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |
|   |                |

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_