


Index No. E 22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
W/16 Corner common to sections 412



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1x36" 1 P.W. BRASS CAP W/16 51 512 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. PINE N. PINE _____
Diameter 7" 10" _____
Bearing N 23 1/2 E S 17 1/2 W _____
Distance 42 LKS 67 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By ROAD SURVEY
Location filed COUNTY BOOK "D" P 104-105
Monument Iron Monument

Evidence of Subsequent Corner Restoration

Year of search 1981 By Walter Curo
Found 1" x 3/16" brass cap monument. Set
2" x 24" brass cap monument.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>W. OAK</u>	<u>W. OAK</u>	<u>W. OAK</u>	<u>N. PINE</u>
<u>10"</u>	<u>7"</u>	<u>6"</u>	<u>20"</u>
<u>N 30 W</u>	<u>S 38 W</u>	<u>S 18 E</u>	<u>S 17 W</u>
<u>81.53'</u>	<u>50.85'</u>	<u>47.06'</u>	<u>44.00'</u>
			<u>(1917 BT)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BUELER SMITH - HWY ENGINEER - 1921
CERTIFICATE - WALT CURO - 1981
Doc. # 2162435

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____