


Index No. F 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5<sup>TH</sup> Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>116</sup> Corner common to sections 11, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1917 N<sup>116</sup>  
Original monument 1x36" I.P. W/BASS S11 | S12  
CAP 1917

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species R. OAK R. OAK  
Diameter 14" 6"  
Bearing N 20 E N 43 W  
Distance 250 LKS 133 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species R. Oak W. Oak W. Oak W. Oak  
Diameter 14" 5" 5" 9"  
Bearing N 43 W N 10 W S 30 W N 60 W  
Distance 87.80' 40.91' 15.32' 42.93'  
(1917 BT)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - WALT Curo - 1981  
Doc. # 262637

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_