Index No. F-G 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

W.C. AP#1 Corner common to sections 11, 12

TR1223, AP#3 1669, AP#4 1226



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1X36" I.P. W/ BRASS CAP

W.C. S11 S12 TR1226 AP4 TR1669 AP3 AP1 TR1223 1917

Bearing Trees

Species			
Diameter			
Bearing			
Distance			

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo

Location filed _____

Monument Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	R. OAK	MAPLE	R. OAK
Diameter	8"	10"	5"
Bearing	S62W	S15W	S60E
Distance	45.88'	20.09'	30.94'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - WALT CURO - 1981

DOC. #2602601a

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____