Index No. H 12

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

SE 1/16 Corner common to sections 9




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1917

Original monument 1 X 36" I.P. W/BRASS CAP

SE 1/16 59
1917

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | CEDAR | CEDAR | | |
| Diameter | 7" | 8" | | |
| Bearing | N60E | S40W | | |
| Distance | 25 LKS | 35 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____