Index No. J 10

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

W1/16 Corner common to sections 9, 16




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1917

Original monument 1X36" L.P.W/BRASS CAP

W1/16 59 / S16 1917

Bearing Trees

| | | | |
|---|---|---|---|
| Species | BALSAM | CEDAR | SET 36" IN GROUND |
| Diameter | 6" | 8" | |
| Bearing | N89E | S80 3/4E | |
| Distance | 405 LKS | 353 LKS | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____