


Index No. J3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 18 Corner common to sections 7, 18



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>SPRUCE</u>	<u>BIRCH</u>	_____	_____
Diameter	<u>10"</u>	<u>10"</u>	_____	_____
Bearing	<u>S36W</u>	<u>N47W</u>	_____	_____
Distance	<u>23 LKS</u>	<u>35 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLD  
Location filed SEC. OF STATE  
Monument SET W.C. TO 1/4 1/67 CH W. SET 1X36" IRON  
W/BRASS CAP 1/4 57 WE  
SIB  
1917

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker  
Found 1" iron monument with brass cap.

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>R. OAK</u>	_____	_____
Diameter	<u>8"</u>	<u>14"</u>	_____	_____
Bearing	<u>N81W</u>	<u>S52 3/4 W</u>	_____	_____
Distance	<u>82 LKS</u>	<u>86 LKS</u>	_____	_____

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Red Oak</u>	<u>Triple Burr Oak</u>	_____	_____
<u>24"</u>	<u>10"</u>	<u>5"</u>	_____	_____
<u>N 39 W</u>	<u>S 78 W</u>	<u>S 66 W</u>	_____	_____
<u>79.85'</u>	<u>104.45'</u>	<u>77.78'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 309832

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_